

## IECEx Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/BAS/QAR06.0017/10** Page 1 of 2

QAR Free Ref. No.: 1112 Status: Issued

Details of change: Reassessment audit completed Date of issue: 2021-09-03

Site(s) audited: The Wolf Safety Lamp Co. Limited Valid until: 2024-06-08

Saxon Road Works

Sheffield Audit date: 2021-06-08 S8 0YA

Issuing ExCB: BAS - SGS Baseefa Limited

Manufacturer: The Wolf Safety Lamp Co. Limited

**United Kingdom** 

Saxon Road Works

Sheffield S8 0YA

Location of **United Kingdom** Manufacturer:

Product information: Torches, Luminaires, lamps

Protection concept: Ex 'd' 'e' 'i' 'm' 't' 'op is'

Related QARs:

GB/BAS/QAR06.0017/00 GB/BAS/QAR06.0017/01 GB/BAS/QAR06.0017/02 GB/BAS/QAR06.0017/03 GB/BAS/QAR06.0017/04 GB/BAS/QAR06.0017/05 GB/BAS/QAR06.0017/06 GB/BAS/QAR06.0017/07 GB/BAS/QAR06.0017/08 GB/BAS/QAR06.0017/09

Related Certificates (manual insertion)::

**IECEx TSA 05.0017X** 

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx BAS 06.0001 issue: 2 IECEx BAS 06.0001 issue: 3 IECEx BAS 06.0001 issue: 1 IECEx BAS 06.0001 issue: 4 IECEx BAS 06.0001 issue: 5 IECEx BAS 06.0001X issue: 6 IECEx BAS 06.0001X issue: 7 IECEx BAS 06.0001X issue: 8 IECEx BAS 06.0023 issue: 0 IECEx BAS 06.0023 issue: 1 IECEx BAS 06.0023 issue: 2 IECEx BAS 06.0023 issue: 3 IECEx BAS 06.0023 issue: 4 IECEx BAS 06.0023 issue: 8 IECEx BAS 06.0023X issue: 5 IECEx BAS 06.0023X issue: 7 IECEx BAS 06.0023X issue: 6 IECEx BAS 06.0089 issue: 0 IECEx BAS 06.0089 issue: 2 IECEx BAS 06.0089 issue: 3 IECEx BAS 06.0089 issue: 1 IECEx BAS 06.0089X issue: 4 IECEx BAS 06.0089X issue: 5 IECEx BAS 06.0089X issue: 6 IECEx BAS 09.0153 issue: 0 IECEx BAS 09.0153 issue: 1 IECEx BAS 09.0153 issue: 2 IECEx BAS 09.0153 issue: 3 IECEx BAS 09.0153X issue: 4 IECEx BAS 09.0153X issue: 5 IECEx BAS 09.0153X issue: 6 IECEx BAS 09.0153X issue: 7 IECEx BAS 10.0023 issue: 0 IECEx BAS 10.0023 issue: 1 IECEx BAS 10.0023 issue: 2 IECEx BAS 10.0023X issue: 3 IECEx BAS 10.0023X issue: 4 IECEx BAS 11.0116 issue: 0 IECEx BAS 11.0116 issue: 1 IECEx BAS 11.0116 issue: 4 IECEx BAS 11.0116X issue: 2 IECEx BAS 11.0116X issue: 3 IECEx BAS 14.0095 issue: 0 IECEx BAS 14.0095 issue: 1 IECEx BAS 15.0033X issue: 0 IECEx BAS 15.0033X issue: 1 IECEx BAS 15.0033X issue: 2 IECEx BAS 16.0073X issue: 0 IECEx BAS 16.0073X issue: 1 IECEx BAS 16.0076X issue: 0 IECEx CML 18.0197X issue: 0 IECEx CML 18.0198X issue: 1 IECEx CML 18.0197X issue: 1 IECEx CML 18.0198X issue: 0 IECEx CML 18.0199X issue: 0 IECEx CML 18.0199X issue: 1 IECEx CML 19.0005X issue: 0 IECEx SIR 10.0016X issue: 0 IECEx SIR 10.0016X issue: 1 IECEx SIR 10.0016X issue: 2

-- Continued on the next page



## IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/BAS/QAR06.0017/10** Page 2 of 2

Related Certificates for previous versions (continued):

IECEx SIR 10.0016X issue: 3	IECEx SIR 10.0016X issue: 4	IECEx SIR 10.0016X issue: 5
IECEx SIR 10.0121 issue: 0	IECEx SIR 10.0121 issue: 1	IECEx SIR 10.0121X issue: 2
IECEx SIR 10.0121X issue: 3	IECEx SIR 12.0070X issue: 0	IECEx SIR 12.0070X issue: 1
IECEx SIR 12.0070X issue: 2	IECEx SIR 12.0070X issue: 3	IECEx SIR 12.0070X issue: 4
IECEx SIR 12.0070X issue: 5	IECEx SIR 12.0070X issue: 6	IECEx SIR 12.0070X issue: 7
IECEx SIR 12.0070X issue: 8	IECEx SIR 15.0115X issue: 0	IECEx SIR 15.0115X issue: 1
IECEx SIR 17.0013X issue: 0	IECEx SIR 17.0013X issue: 1	IECEx SIR 18.0028X issue: 0

Comments: